



EAO-ESA-ELEKTRO GMBH  
MR D HUFENHAUSER  
STAUFFENBERGSTRASSE 19  
POSTFACH 10005  
08201  
AUERBACH/VOGTLAND FED REP GERMANY

Your most recent listing is shown below. Please review this information and report any inaccuracies to the UL Engineering staff member who handled your Assignment.

NKCR  
Auxiliary Devices

August 16, 1994

EAO-ESA-ELEKTRO GMBH , AUERBACH/VOGTLAND E148904 (M)  
FED REP GERMANY

Contact assembly, Cat. No. 44 followed by 1 or 2, followed by 1, 2, 3, 4, 5 or 6, followed by 1.  
Lamp assembly, Cat. No. 44 followed by 52, followed by 4 or 5.  
Pushbutton actuator, Cat. No. 44 followed by 7, followed by 01, 02, 03, 04, 05, 06, 07, 10, 11,  
12, 13, 20, 22, 24, 25, 26, 27, 30, 32, 34, 35, 36, 37, 42, 44, 45, 46, 47, 50 or 51, followed by  
2 or 6, followed by 0, 1, 2, 3, 4, 5, 6, 7, 8 or 9.  
Pushbutton hole plug, Cat. No. 44 followed by 9, followed by 14 or 15.  
Transformer assembly, Cat. No. 44 followed by 9, followed by 70, 71, 72, 75, 76, 77, 80, 81,  
82, 85, 86 or 87.

STAUFFENBERGSTRASSE 19 POSTFACH 10005 08201  
LOOK FOR LISTING MARK ON PRODUCT

Replaces E148904 dated September 9, 1993.  
733814001 Underwriters Laboratories Inc.®

F11/0223551  
216

For information on placing an order for UL Listing Cards in a 3 x 5 inch card format, please refer to the enclosed ordering information.

UNDERWRITERS LABORATORIES INC.

A not-for-profit organization dedicated to public safety and committed to quality service

333 Pfingsten Road  
Northbrook, Illinois 60062-2096, USA  
708/272-8800  
Telex: 6502543343  
FAX No. (708) 272-8129

1285 Walt Whitman Road  
Melville, L.I., New York 11747-3081, USA  
516/271-8200  
Telex No. 6852015  
FAX No. (516) 271-8259

1655 Scott Blvd.  
Santa Clara, California 95050-4169, USA  
408/985-2400  
FAX No. (408) 296-3256

12 Laboratory Drive  
P.O. Box 13995  
Research Triangle Park,  
North Carolina 27709-3995, USA  
919/549-1400  
Telex No. 4937928  
FAX No. (919) 549-1842